




steel part is strong enough  
and it does not broke even I  
bent it with high stress

Pilot-RC will send you the  
stainless steel part so you can  
replace. please do not fly it  
before you replace it.

**For FC1 elevator and  
VT system push rod**

the brass part on the carbon  
tube rod maybe not strong  
enough. it maybe broken  
from the red position









Heat the brass part by hot gun or hairdryer















